1

#### DESCRIPTION

#### BRUSHLESS MOTOR

Technical Field

The invention relates to a brushless motor, or in particular to a structure of a brushless motor for transferring heat generated in switching elements thereof.

### Background Art

15

20

A brushless motor needs switching elements for turning on or off electric power to be supplied to coils of the stator. Because the switching elements generate heat much, it is necessary to let the heat out.

In an example of a structure of a brushless motor for transferring the heat generated in the switching elements, a base of a circuit board provided in the brushless motor is made of a metal, and the base is fixed to stator iron cores (for example, Japanese Patent laid open Publication 4-161037/1992). The heat generated in the switching elements is conducted to the base of the circuit board and further to the stator iron cores. The stator iron cores have a function similar to radiation fins, and the heat is radiated effectively through the stator iron cores.

However, because the heat generated in the base conducts through the metallic base of the circuit board,

the temperature of the circuit board becomes higher. Therefore, it is a problem that components other than the switching elements mounted on the circuit board are affected by the heat.

5

# Disclosure of Invention

An object of the invention is to provide a brushless motor which can effectively transfer the heat generated by the switching elements in the brushless motor.

A brushless motor according to the invention has a 10 stator, a rotor and a circuit board 4 for controlling rotation of the rotor. The stator has stator iron cores 1 and coils 2 wound around the cores. Switching elements 3 for turning on and off electric power to be supplied to the coils 2 for the stator are mounted to the circuit board 4. 15 Further it has a heat-radiating member 5 fixed to the stator iron cores 1. Then the heat generated in the switching elements are diverged effectively to the heatradiating member 5 and further to the stator iron cores 1, which have a function of heat-radiating fins for effective 20 heat radiation. Because the heat is radiated by the heatradiating member other than the circuit board, components other than the switching elements 3 on the circuit board 4 . are not affected by the heat.

Preferably, in the brushless motor, two bearings 9, 10

3

supports a shaft 8 of the rotor 7 rotatably at two ends of the shaft 8, and one of the bearings is supported by the heat-radiating member 5. Because one of the bearings for supporting the shaft is supported by the heat-radiating member 5, the length of the shaft 8 of the rotor 7 can be shortened, and the brushless motor can be made compact and have a light weight.

5

10

25

Preferably, in the brushless motor, the switching elements 3 are contacted to the heat-radiating member 5.

Thus the heat generated in the switching elements is radiated effectively.

Preferably, in the brushless motor, the iron cores 1 are screwed to the heat-radiating member 5. By using the screws 12, the heat conduction is improved.

Preferably, in the brushless motor, each of the iron cores 1 of the stator has a bump protruding from an outside plane thereof, and the bump has a hole for screwing the iron cores to the heat-radiating member 5. The portion is also used for aligning the stators to a motor case of the motor.

Preferably, the brushless motor further has a biasing member 13 which pushes the switching elements 3 simultaneously to the heat-radiating member 5. Thus the heat generated in the switching elements is conducted effectively to the switching elements and further to the

heat-radiating member 5, so that the temperature rise is suppressed. Further, only one biasing elements pushes the switching elements 3, increase in the number of the components in the motor is kept minimum.

Preferably, the brushless motor further has a cooling fan 11 for cooling the switching elements 3 and the coils 2, and the cooling fan 11 is fixed to a shaft 8 of the rotor 7. When the rotor is rotated, the cooling fan 11 sends air towards the switching elements 3 and the coils 2 for cooling, and this suppresses the temperature rise in the motor. Thus, the brushless motor can be made more compact and have a lighter weight.

## Brief Description of Drawings

- Fig. 1 is a sectional view of a brushless motor according to an embodiment of the invention.
  - Fig. 2 is a perspective view of the brushless motor shown in Fig. 1.
- Fig. 3 is another perspective view of the brushless 20 motor along a direction different from that in Fig. 2.
  - Fig. 4 is a sectional view of a brushless motor according to another embodiment of the invention.
  - Fig. 5 is a perspective view of the brushless motor shown in Fig. 4.

Best Mode for Carrying Out the Invention

5

10

A brushless motor according to the invention are explained below with reference to the appended drawings, wherein like reference characters designate like or corresponding parts throughout the several views.

5

Figs. 1 to 3 show a brushless motor of a first embodiment of the invention. As shown in Fig. 1, the brushless motor of an inner rotor type has a rotor 7 in a stator 6. The rotor 7 is fixed to a shaft 8 supported by two bearings 9 and 10. The stator 6 has a cylindrical insulator 14 made of a material such as resin, six iron cores 1 press fit therein, and six coils 2 wound around the iron cores 1. The iron cores 1 of the stator 6 are composed of layered electromagnetic steel plates.

15 A circuit board 4 for driving the rotor 7 is arranged near a side of the stator 6, and switching elements 3 such as field effect transistors are mounted on the circuit board 4 for turning on or off electric power to be supplied to the coils 2. A heat-radiating member 5 made of a metal 20 such as aluminum having high thermal conductivity is connected to the iron cores 1, and it is also fixed with screws 15 to the circuit board 4. A lead 16 is provided for supplying electric power to the switching elements 3 and the circuit board 4. The coils 2 of the stator 6 are 25 connected electrically to the circuit board 4. The heat-

5

10

20

25

radiating member 5 is connected to a side of the stator iron cores 1, and the switching elements 3 are contacted to the heat-radiating member 5.

An iron core 17 of the rotor 7 is arranged inside the stator 6 with a gap between them, and magnets 18 are fixed to the iron core 17 with an adhesive or the like. shaft 8 of the rotor 7 is inserted at the center of the rotor iron core 17 as an integral body. The bearings 9, 10 such as ball bearings support the shaft 8 at two ends thereof, and a pinion 19 is mounted to an end of the shaft The stator 6 and the rotor 7 constructed as mentioned above are enclosed in a motor case (not shown) of the motor, and the bearings 9 and 10 are supported by the motor case.

In the above-mentioned motor, an electric current flows in the order of the lead 16, the circuit board 4, the 15 switching elements 3, the circuit board 4 and the coils 2, to rotate the shaft 8 of the rotor 7. The heat generated in the switching elements 3 is radiated effectively both from the heat-radiating member 5 and from the stator iron The stator iron cores 1 play a role of heatradiating ribs for effective heat radiation, and the heatradiating member 5 conducts heat therethrough and radiates heat from the surface thereof. Because the heat can be radiated by the heat-radiating member 5 other than the circuit board 4, it is prevented that components other than

WO 2004/107536

5

10

the switching elements 3 mounted on the circuit board 4 are affected by the heat.

A cooling fan 11 is fixed onto the pinion 19 connected the shaft 8 of the rotor 7 at a side opposite to the heat-radiating member 5. When the shaft 8 is driven, the cooling fan 11 is also rotated with the shaft 8 to blow air, so that ambient air is taken into for cooling from the side of the heat-radiating member 5 and is exhausted through the switching elements 3 and the coils 2 towards the outside. Therefore, by driving the cooing fan 11, air taken into the motor cools the switching elements 3 and the coils 2 successively. Thus the motor can be made more compact with a lighter weight, and it can be prevented to deteriorate the characteristics thereof.

Bumps 20 swelled towards the outside are provided on an external plane of each of the stator iron cores 1. They have throughholes, and screws 12 are inserted therein to engage the top thereof to the heat-radiating member 5. Thus, the stator iron cores 1 are connected thermally to the heat-radiating member 5. The bumps 20 of the iron cores 1 can also be used for alignment with the motor case. Because the iron cores 1 are fixed with the screws 12 to the heat-radiating member 5, the heat conduction through the heat-radiating member 5 is enhanced.

A clip 13 is provided at the outside of the switching

5

10

15

20

25

8

elements 3 for biasing the switching elements 3 to contact with the heat-radiating member 5. The clip 13 is made of a metal such as stainless steel or copper having good elasticity and good heat radiation. Because the switching elements 3 are pressed by the clip 13 to the heat-radiating member 5, the temperature rise of the switching elements 3 can be suppressed. Because the clip 13 is made of a metal, the heat radiation is improved. The clip 13 has a plurality of pressing fingers 13a, each of which abuts on the switching elements 3 so that the only clip 13 presses the switching elements 3 simultaneously. Because one clip 13 is used for pressing the plurality of switching elements 3, increase in the number of the components mounted on the circuit board 4 can also be kept small. The clip 13 has an M-character-like shape when observed in a section, and the center of the clip 13 is contacted and fixed with screws 21 to the heat-radiating member 5. Then the displacement of the clip 13 can be increased. By screwing the center of the clip 13 with the M-character-like section to the heatradiating member 5 with the screws 21, the pressure applied to the switching elements 3 is increased so as to improve the heat conduction between them, and the heat can be radiated more effectively.

Figs. 4 and 5 show a brushless motor according to another embodiment of the invention. Only different points

9

from the brushless motor shown in Figs. 1 to 3 are explained here. In this motor, the heat-radiating member 5 has a concave 22 for fitting and supporting the bearing 9 for the shaft 8. The other bearing 10 is supported by the motor case (not shown) of the motor. Because one of the bearings 9 is supported by the heat-radiating member 5, the length of the shaft 8 can be shortened. Thus the motor can be made more compact with a lighter weight.

5

15

In the above-mentioned brushless motors according to the invention, the heat generated by the switching elements 10 is conducted to the heat-radiating member and from the heat-radiating member to the stator iron cores effectively. The stator iron cores have a function as heat-radiating fins for effective heat radiation. Further, because the heat is radiated by the heat-radiating member other than the circuit board, it is prevented that components on the circuit board other than the switching elements affected by the heat.

Although the present invention has been fully 20 described in connection with the preferred embodiments thereof with reference to the accompanying drawings, it is to be noted that various changes and modifications are apparent to those skilled in the art. Such changes and modifications are to be understood as included within the scope of the present invention as defined by the appended 25

claims unless they depart therefrom.